






Spare Parts / Ersatzteile / Pièces de rechange / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Pieśe de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



1	A 962 872 AA	22	A 961 073 AA
3	A 962 998 NU	25	A 960 400 AA
4	A 962 870 AA	28	A 860 780 AA
5	A 962 871 AA	30	A 860 778 NU
6	A 963 427 NU	31	A 860 874 AA
7	A 962 229 NU	33	A 860 807 AA
8	A 962 230 NU	34	B 9442 AA
9	A 963 432 NU	35	F 960 891 AA
10	A 962 563 NU	36	A 860 873 AA
12	A 962 568 NU		
14	A 962 529 NU		
15	A 961 332 NU		
18	A 962 594 NU		
19	A 961 810 NU		
20	A 962 595 NU		
21	B 960 242 AA		




XX = AA, AD...



CERATHERM 100

A 5778 .. A 5955 ..





0215 / A 866 489 40
 (+ A 865 612)
 Made in Germany



Ideal Standard International BVBA
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com





P bar	T °C	Q (3 bar) l/min	
0,5	MAX. 80	8	
1	65	11	
5	55	20	